PowerMadd

Handguard fitment issues

Our handguard mounts kits require ½" of space on your handlebars near your grips. You may need to slide your control left or right to free up the space required.

Below are situations where we have found some fitment issues.

ATV'S

Kawasaki Brute Force

Sentinel Handguards: Use 34452 no issues

Star Series Handguards: Use 34252 Issues (see below)





Left Side Right Side

The left side needs to be mounted under the lever, and the right side needs to be mounted over the lever. Call PowerMadd at 651-462-8465 or email techsupport@powermadd.com and we will send you another bracket so you can mount them this way.

Kawasaki KFX700

Due to the large rotating shifter on the left side of the handlebars there is no space for our standard mount kits. The 34269 Tri-Mount mounts to the upsweep section of the handle bar where there is space.

Sentinel: Use 34269 Star Series: Use 34269



Left side of KFX700 handle bars has no space for our standard ATV mount kit.

Yamaha Grizzly 700 2007-current

Sentinel: 34269 or 34452 (click here for model

specific instructions)

Star Series Handguards: use 34269 mount kit



Snowmobiles

Arctic Car 2012-2018 Pro Cross/Pro climb

Sentinel: 34454

Star Series: No options

Due to the size of the brake reservoir there is no room for our standard mounting bracket.



Arctic Cat 2019-current Pro Cross/Pro Climb

Sentinel: 34456

Star Series: No options

Due to the size of the brake reservoir there is no room for $% \left\{ 1\right\} =\left\{ 1\right\}$

our standard mounting bracket.



Polaris 2015-current Axys chassis

Sentinel: 34454

Star Series: No options

Due to the size of the brake reservoir there is no room for

our standard mounting bracket.



Polaris 2021-current Matrix chassis

Sentinel: 34456

Star Series: No options

Due to the size of the brake reservoir there is no room for

our standard mounting bracket.



Polaris RMK 2008 Mountain

Sentinel: 34269 Star Series: 34269

Some models have a welded tab on the bars to mount the grab bar; this does not leave enough room for the 34250 Snowmobile Mount Kit mounting bracket.

Use the 34269 Tri-Mount which mounts past the bend in the bars on the down-slope where there is plenty of room



Yamaha Viper Sentinel: 34450 Star Series: 34250

Will only work with low windshields. If you have raised your handlebars or have a windshield taller then a low you will have clearance issues between the handguard and windshield.





<u>Yamaha 2013-2018 SR Viper and Sidewinder</u> <u>Sentinel: 34454</u>

Star Series: No option

Due to the size of the brake reservoir there is no room for

our standard mounting bracket.



Yamaha 2019-current SR Viper and Sidewinder

Sentinel: 34456

Star Series: No option

Due to the size of the brake reservoir there is no room for

our standard mounting bracket.

